

# Malicious Code Execution Vulnerability in Multiple FA Engineering Software Products

Release date: July 30, 2020

Last update date: January 14, 2021

Mitsubishi Electric Corporation

## ■ Overview

Multiple Mitsubishi Electric FA engineering software products have a malicious code execution vulnerability. A malicious attacker could use this vulnerability to obtain information, tamper the information, cause a denial-of-service (DoS), and so on. The product names and versions affected by the vulnerability are listed below.

## ■ Affected Products

<Products and Versions>

C Controller Interface Module utility, all versions  
C Controller module setting and monitoring tool, all versions  
CC-Link IE Control Network Data Collector, all versions  
CC-Link IE Field Network Data Collector, all versions  
CPU Module Logging Configuration Tool, version 1.100E and prior  
CW Configurator, version 1.010L and prior  
Data Transfer, version 3.42U and prior  
EZSocket, all versions  
FR Configurator SW3, all versions  
FR Configurator2, all versions  
GT Designer2 Classic, all versions  
GT Designer3 Version1 (GOT1000), version 1.241B and prior  
GT Designer3 Version1 (GOT2000), version 1.241B and prior  
GT SoftGOT1000 Version3, version 3.200J and prior  
GT SoftGOT2000 Version1, version 1.241B and prior  
GX Developer, version 8.504A and prior  
GX LogViewer, version 1.100E and prior  
GX Works2, all versions  
GX Works3, version 1.063R and prior  
M\_CommDTM-IO-Link, all versions  
MELFA-Works, all versions  
MELSEC WinCPU Setting Utility, all versions  
MELSOFT Complete Clean Up Tool, all versions  
MELSOFT EM Software Development Kit, all versions  
MELSOFT iQ AppPortal, version 1.17T and prior  
MELSOFT Navigator, all versions  
MI Configurator, all versions  
Motion Control Setting, version 1.005F and prior  
Motorizer, version 1.005F and prior  
MR Configurator2, all versions  
MT Works2, all versions  
MTConnect Data Collector, all versions  
MX Component, version 4.20W and prior  
MX MESInterface, version 1.21X and prior  
MX MESInterface-R, version 1.12N and prior  
MX Sheet, version 2.15R and prior  
Network Interface Board CC IE Control utility, all versions  
Network Interface Board CC IE Field Utility, all versions  
Network Interface Board CC-Link Ver.2 Utility, all versions  
Network Interface Board MNETH utility, all versions  
Position Board utility 2, all versions  
PX Developer, all versions  
RT ToolBox2, all versions  
RT ToolBox3, all versions  
Setting/monitoring tools for the C Controller module, all versions  
SLMP Data Collector, all versions

#### <How to Check the Versions>

Refer to the manual or help of each product.

#### ■ Description

Multiple Mitsubishi Electric FA engineering software products have a malicious code execution vulnerability (CVE-2020-14521). This is because some files in the product have improper permissions, and a malicious attacker could replace them with malicious files (CWE-428).

#### ■ Impact

A malicious attacker could use this vulnerability to obtain information, tamper the information, cause a denial-of-service (DoS), and so on.

#### ■ Countermeasures

Download the latest version of each software product from the following site and update it:

<https://www.mitsubishielectric.com/fa/#software>

The fixed software products and versions are as follows:

#### <Products and Versions>

CPU Module Logging Configuration Tool, version 1.106K or later

CW Configurator, version 1.011M or later

Data Transfer, version 3.43V or later

GT Designer3 Version1 (GOT1000), version 1.245F or later

GT Designer3 Version1 (GOT2000), version 1.245F or later

GT SoftGOT1000 Version3, version 3.245F or later

GT SoftGOT2000 Version1, version 1.245F or later

GX Developer, version 8.505B or later

GX LogViewer, version 1.106K or later

GX Works3, version 1.065T or later

MELSOFT iQ AppPortal, version 1.20W or later

Motion Control Setting, version 1.006G or later

Motorizer, version 1.010L or later

MX Component, version 4.21X or later

MX MESInterface, version 1.22Y or later

MX MESInterface-R, version 1.13P or later

MX Sheet, version 2.16S or later

#### <How to Update the Products>

Refer to the manual or help of each product.

#### ■ Mitigations

For customers who are using a product that has not released a fixed version or who cannot immediately update the product, Mitsubishi Electric recommends that customers take the following mitigation measures to minimize the risk of exploiting this vulnerability:

-If a "File Name Warning" message is displayed when starting Windows, take appropriate measures according to the instructions in the message, such as changing a file name, and then install or operate the products.

-Operate the products under an account that does not have administrator's privileges.

-Install an antivirus software in your personal computer using the products.

-Restrict network exposure for all control system devices or systems to the minimum necessary, and ensure that they are not accessible from untrusted networks and hosts.

-Locate control system networks and remote devices behind firewalls and isolate them from the business network.

-Use Virtual Private Network (VPN) when remote access is required.

#### ■ Acknowledgements

Mitsubishi Electric would like to thank Mashav Sapir of Claroty who reported this vulnerability.

#### ■ Contact Information

Please contact your local Mitsubishi Electric representative.

#### ■ Update history

January 14, 2021

Added MELSOFT iQ AppPortal, MX Component and MX Sheet that have been fixed to “Countermeasures”.

November 5, 2020

Added Data Transfer, GT Designer3 Version1(GOT1000), GT Designer3 Version1(GOT2000), GT SoftGOT1000 Version3, GT SoftGOT2000 Version1, MX MESInterface, and MX MESInterface-R that have been fixed to “Countermeasures”.