Denial-of-Service(DoS) Vulnerability and Client-side Script Injection Vulnerability in multiple consumer electronics products

Release date: September 29, 2022 Mitsubishi Electric Corporation

Overview

A Denial of Service (DoS) vulnerability due to use of freed memory (CWE-416) and a client-side script injection vulnerability due to cross-site scripting (CWE-79) exist in multiple consumer electronics products manufactured by Mitsubishi Electric Corporation. These vulnerabilities allow a malicious attacker to cause a DoS Condition (CVE-2022-29859) on the products or make it respond with a message containing an arbitrary malicious script, which may be executed on the browser, resulting in information disclosure, etc. (CVE-2022-33322). The following products are affected by these vulnerabilities, please take countermeasures, mitigations and workarounds.

CVSS Score

CVE-2022-29859	CVSS:3.1/AV:A/AC:H/PR:N/UI:N/S:U/C:N/I:N/A:L	Base Score:3.1
CVE-2022-33322	CVSS:3.1/AV:N/AC:H/PR:N/UI:R/S:U/C:H/I:H/A:N	Base Score:6.8

Description

Multiple consumer electronics products manufactured by Mitsubishi Electric have a Denial of Service (DoS) vulnerability (CVE-2022-29859) due to the following defect in a DHCP process in OSS (open source software) and a client-side script injection vulnerability (CVE-2022-33322) due to the following defect caused by improper input filtering/validation on a web server.

CVE-2022-29859: Use of freed memory (CWE-416)

CVE-2022-33322: Cross-site scripting (CWE-79)

Impact

An attacker can cause a DoS Condition by sending specially crafted message to the target device, or making it respond with a message containing an arbitrary malicious script, which may be executed on the browser, resulting in information disclosure, etc.

 $\blacksquare\ensuremath{\mathsf{Affected}}$ products, countermeasures, and mitigations or workarounds

1] [Wi-Fi Interface and Air Conditioning] model number	Countermeasures and Mitigation/Workarounds
Wi-Fi Interface:	<pre>(Impact></pre>
MAC-587IF-E	These vulnerabilities allow a malicious attacker to cause a DoS Condition or
MAC-587IF2-E	the products or make it respond with a message containing an arbitrary
MAC-507IF-E	malicious script, which may be executed on the browser, resulting in information
MAC-588IF-E	disclosure, etc.
S-MAC-002IF	
Air Conditioning:	<countermeasures></countermeasures>
MSXY-FP05/07/10/13/18/20/24VGK-SG1	Please carry out the mitigations below.
MSY-GP10/13/15/18/20/24VFK-SG1	
MSZ-AP25/35/42/50VGK-E1	<mitigations workarounds=""></mitigations>
MSZ-AP15/20/25/35/42/50/60/71VGK-E2	1. Check if the router settings are as follows.
MSZ-AP25/35/42/50/60/71VGK-E3	1-1. Set encryption key of wireless LAN which can hardly be identified. If ke
MSZ-AP25/35/42/50VGK-E7	is changed from initial setting, avoid consecutive numbers and guessable
MSZ-AP25/35/42/50VGK-E8	MAC address, and combine letters and numbers.
MSZ-AP25/35/42/50VGK-EN1	1-2. Do not use WEP encryption algorithm or Open authentication.
MSZ-AP25/35/42/50VGK-EN2	1-3. If you change the router settings, hide its presence on the internet in orde
MSZ-AP25/35/42/50VGK-EN3	to make it difficult for unauthorized access.
MSZ-AP25/35/42/50VGK-ER1	(e.g. Set to not respond to PING request)
MSZ-AP15/20/25/35/42/50/60/71VGK-ER2	1-4. Set password for the router's Management portal, which is difficult to be
MSZ-AP25/35/42/50/60/71VGK-ER3	identified.
MSZ-AP25/35/42/50VGK-ET1	1–5. Install the wireless LAN router in a location where it cannot be touched b
MSZ-AP15/20/25/35/42/50/60/71VGK-ET2	outsiders. Do not open the network to unspecified third parties, such a
MSZ-AP25/35/42/50/60/71VGK-ET3	by offering it as free Wi-Fi.
MSZ-AY25/35/42/50VGK-E1	1-6. Do not let any third parties know the URL (IP address or host name) o
MSZ-AY25/35/42/50VGK-E6	the relevant product.
MSZ-AY25/35/42/50VGK-ER1	
MSZ-AY25/35/42/50VGK-ET1	2.Check the following when using a computer or tablet, etc. at home.
MSZ-AY25/35/42/50VGK-SC1	2-1. Update Antivirus software to the latest version.
MSZ-AY25/35/42/50VGKP-E6	2-2. Do not open or access suspicious attachment file or linked URL.
MSZ-AY25/35/42/50VGKP-ER1	
MSZ-AY25/35/42/50VGKP-ET1	
MSZ-AY25/35/42/50VGKP-SC1	
MSZ-BT20/25/35/50VGK-E1	
MSZ-BT20/25/35/50VGK-E2	
MSZ-BT20/25/35/50VGK-E2 MSZ-BT20/25/35/50VGK-E3	
MSZ-BT20/25/35/50VGK-ER1	
MSZ-BT20/25/35/50VGK-ER2	
MSZ-BT20/25/35/50VGK-ET1	
MSZ-BT20/25/35/50VGK-ET2	
MSZ-BT20/25/35/50VGK-ET3	
MSZ-EF18/22/25/35/42/50VGKW-E1	
MSZ-EF18/22/25/35/42/50VGKB-E1	
MSZ-EF18/22/25/35/42/50VGKS-E1	
MSZ-EF18/22/25/35/42/50VGKW-E2	
MSZ-EF18/22/25/35/42/50VGKB-E2	
MSZ-EF18/22/25/35/42/50VGKS-E2	
MSZ-EF22/25/35/42/50VGKW-ER1	
MSZ-EF22/25/35/42/50VGKB-ER1	
MSZ-EF22/25/35/42/50VGKS-ER1	
MSZ-EF22/25/35/42/50VGKW-ER2	
MSZ-EF22/25/35/42/50VGKB-ER2	
MSZ-EF22/25/35/42/50VGKS-ER2	
MSZ-EF22/25/35/42/50VGKW-ET1	
MSZ-EF22/25/35/42/50VGKB-ET1	
MSZ-EF22/25/35/42/50VGKS-ET1	
MSZ-EF22/25/35/42/50VGKW-ET2	
MSZ-EF22/25/35/42/50VGKW-ET2 MSZ-EF22/25/35/42/50VGKB-ET2	
MSZ-EF22/25/35/42/50VGKS-ET2	
MSZ-EF22/25/35/42/30VGKS-E12 MSZ-FT25/35/50VGK-E1	
MSZ-FT25/35/50VGK-E2	
MSZ-FT25/35/50VGK-ET1	
MSZ-FT25/35/50VGK-SC1	

MSZ-FT25/35/50VGK-SC2 MSZ-HR25/35/42/50/60/71VFK-E1 MSZ-HR25/35/42/50VFK-E6 MSZ-HR25/35/42/50/60/71VFK-ER1 MSZ-HR25/35/42/50/60/71VFK-ET1 MSZ-LN18/25/35/50/60VG2W-E2 MSZ-LN18/25/35/50/60VG2W-E3 MSZ-LN25/35/50VG2W-EN2 MSZ-LN18/25/35/50/60VG2W-ER2 MSZ-LN25/35/50/60VG2W-ER3 MSZ-LN18/25/35/50/60VG2W-ET2 MSZ-LN25/35/50/60VG2W-ET3 MSZ-LN18/25/35/50/60VG2V-E2 MSZ-LN18/25/35/50/60VG2V-E3 MSZ-LN25/35/50VG2V-EN2 MSZ-LN25/35/50/60VG2V-ER2 MSZ-LN25/35/50/60VG2V-ER3 MSZ-LN25/35/50/60VG2V-ET2 MSZ-LN25/35/50/60VG2V-ET3 MSZ-LN18/25/35/50/60VG2B-E2 MSZ-LN18/25/35/50/60VG2B-E3 MSZ-LN25/35/50VG2B-EN2 MSZ-LN25/35/50/60VG2B-ER2 MSZ-LN25/35/50/60VG2B-ER3 MSZ-LN25/35/50/60VG2B-ET2 MSZ-LN25/35/50/60VG2B-ET3 MSZ-LN18/25/35/50/60VG2R-E2 MSZ-LN18/25/35/50/60VG2R-E3 MSZ-LN25/35/50VG2R-EN2 MSZ-LN25/35/50/60VG2R-ER2 MSZ-LN25/35/50/60VG2R-ER3 MSZ-LN25/35/50/60VG2R-ET2 MSZ-LN25/35/50/60VG2R-ET3 MSZ-LN18/25/35/50VG2W-SC1 MSZ-LN25/35/50VG2V-SC1 MSZ-LN25/35/50VG2B-SC1 MSZ-LN25/35/50VG2R-SC1 MSZ-RW25/35/50VG-E1 MSZ-RW25/35/50VG-ER1 MSZ-RW25/35/50VG-ET1 MSZ-RW25/35/50VG-SC1 MSZ-AP22/25/35/42/50/61/70/80VGKD-A1 MSZ-AP22/25/35/42/50/60/71/80VGKD-A2 MSZ-EF22/25/35/42/50VGKW-A1 MSZ-EF22/25/35/42/50VGKB-A1 MSZ-EF22/25/35/42/50VGKS-A1 MSZ-LN25/35/50/60VG2V-A2 MSZ-LN25/35/50/60VG2B-A2 MSZ-LN25/35/50/60VG2R-A2 MFZ-GXT50/60/73VFK MFZ-XT50/60VFK MSZ-EZA09/12VAK MSZ-EXA09/12VAK MSZ-GZY09/12/18VFK MSZ-KY09/12/18VFK MSZ-WX18/20/25VFK MSZ-ZY09/12/18VFK Versions 35.00 and prior of the above models are affected.

*Contact information

Please contact your local Mitsubishi Electric representative.

<Inquiries> https://www.mitsubishielectric.com/en/contact/room-air-conditioners.html

[2] [Air Purifier]

model number	Countermeasures and Mitigation/Workarounds
MA-EW85S-E	<impact></impact>
MA-EW85S-UK	These vulnerabilities allow a malicious attacker to cause a DoS Condition
	on the products or make it respond with a message containing an
Versions 80.00 and prior of the above models	arbitrary malicious script, which may be executed on the browser,
are affected.	resulting in information disclosure, etc.
	<countermeasures></countermeasures>
	Please carry out the mitigations below.
	<mitigations workarounds=""></mitigations>
	1.Check if the router settings are as follows.
	1-1. Set encryption key of wireless LAN which can hardly be identified
	If key is changed from initial setting, avoid consecutive numbers and
	guessable MAC address, and combine letters and numbers.
	1-2. Do not use WEP encryption algorithm or Open authentication.
	1-3. If you change the router settings, hide its presence on the internet
	in order to make it difficult for unauthorized access.
	(e.g. Set to not respond to PING request)
	1-4. Set password for the router's Management portal, which is difficult to be identified.
	1-5. Install the wireless LAN router in a location where it cannot be
	touched by outsiders. Do not open the network to unspecified third parties, such as by offering it as free Wi-Fi.
	1–6. Do not let any third parties know the URL (IP address or host name
	of the relevant product.
	2.Check the following when using a computer or tablet, etc. at home.
	2-1. Update Antivirus software to the latest version.
	2-2. Do not open or access suspicious attachment file or linked URL.

*Contact information

Please contact your local Mitsubishi Electric representative.

<Inquiries> https://www.mitsubishielectric.com/en/products-solutions/home/index.html