

Authentication Bypass Vulnerability in WEB Server Function on MELSEC Series

Release date: January 17, 2023

Last update date: April 18, 2023

Mitsubishi Electric Corporation

■ Overview

An authentication bypass vulnerability exists in the WEB server function of the MELSEC iQ-F/iQ-R Series. An unauthenticated remote attacker may be able to access the WEB server function by guessing the random numbers used for authentication from several used random numbers (CVE-2022-40267).

The product names and firmware versions affected by this vulnerability are listed below.

■ CVSS¹

CVE-2022-40267 CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:N/I:H/A:N Base Score 5.9

■ Affected products

The following products are affected:

Series	Product name	Version	
MELSEC iQ-F Series	FX5U-xMy/z x=32,64,80, y=T,R, z=ES,DS,ESS,DSS	Serial number 17X**** or later Serial number 179**** and prior	1.280 and prior 1.074 and prior
	FX5UC-xMy/z x=32,64,96, y=T, z=D,DSS	Serial number 17X**** or later Serial number 179**** and prior	1.280 and prior 1.074 and prior
	FX5UC-32MT/DS-TS, FX5UC-32MT/DSS-TS, FX5UC-32MR/DS-TS		1.280 and prior
	FX5UJ-xMy/z x=24,40,60, y=T,R, z=ES,ESS		1.042 and prior
	FX5UJ-xMy/ES-A* x=24,40,60, y=T,R		1.043 and prior
	FX5S-xMy/z x=30,40,60,80, y=T,R, z=ES,ESS		1.003 and prior
	MELSEC iQ-R Series	R00/01/02CPU R04/08/16/32/120(EN)CPU	33 and prior 66 and prior

* These products are sold in limited regions.

Please refer to the following manual for how to check the version.

- "15.3 Troubleshooting Using the Engineering Tool" - "Module diagnostics" in the MELSEC iQ-F FX5S/FX5UJ/FX5U/FX5UC User's Manual (Hardware)
- "Appendix 1 Checking Production Information and Firmware Version" in the MELSEC iQ-R Module Configuration Manual

Please download the manual from the following URL.

<https://www.mitsubishielectric.com/fa/download/index.html>

■ Description

An authentication bypass vulnerability exists in the WEB server function of the MELSEC iQ-F/iQ-R Series due to predictable seed in pseudo-random number generator(CWE-337²).

■ Impact

An unauthenticated remote attacker may be able to access the WEB server function by guessing the random numbers used for authentication from several used random numbers.

¹ <https://www.first.org/cvss/v3.1/specification-document>

² <https://cwe.mitre.org/data/definitions/337.html>

■ Countermeasures

The following products have been fixed.

Series	Product name	Version	
MELSEC iQ-F Series	FX5U-xMy/z x=32,64,80, y=T,R, z=ES,DS,ESS,DSS	Serial number 17X**** or later	1.281 or later
		Serial number 179**** and prior	1.075 or later
	FX5UC-xMy/z x=32,64,96, y=T, z=D,DSS	Serial number 17X**** or later	1.281 or later
		Serial number 179**** and prior	1.075 or later
	FX5UC-32MT/DS-TS, FX5UC-32MT/DSS-TS, FX5UC-32MR/DS-TS		1.281 or later
	FX5UJ-xMy/z x=24,40,60, y=T,R, z=ES,ESS		1.044 or later
	FX5UJ-xMy/ES-A* x=24,40,60, y=T,R		1.045 or later
FX5S-xMy/z x=30,40,60,80, y=T,R, z=ES,ESS		1.004 or later	
MELSEC iQ-R Series	R00/01/02CPU	34 or later	
	R04/08/16/32/120(EN)CPU	67 or later	

* These products are sold in limited regions. For how to get the fixed version, please contact your local Mitsubishi Electric representative.

Please download fixed firmware update file from the following site and update the firmware.

<https://www.mitsubishielectric.com/fa/download/index.html>

Please refer to the following product manual for how to update firmware.

- "5 FIRMWARE UPDATE FUNCTION" in the MELSEC iQ-F FX5 User's Manual (Application)
- MELSEC iQ-R Module Configuration Manual "Appendix 2 Firmware Update Function"

■ Mitigations/Workarounds

Mitsubishi Electric recommends that customers take the following mitigation measures to minimize the risk of exploiting this vulnerability:

- Use a firewall or virtual private network (VPN), etc. to prevent unauthorized access when Internet access is required.
- Use within a LAN and block access from untrusted networks and hosts through firewalls.
- Use IP filter function* to block access from untrusted hosts.

*: For details on the IP filter function, please refer to the following manual for each product.

"12.1 IP Filter Function" in the MELSEC iQ-F FX5 User's Manual (Ethernet Communication)

"1.13 Security" - "IP filter" in the MELSEC iQ-R Ethernet User's Manual(Application)

■ Acknowledgement

Mitsubishi Electric would like to thank Matt Wiseman of Cisco Talos who reported this vulnerability.

■ Contact information

Please contact your local Mitsubishi Electric representative.

<Inquiries | MITSUBISHI ELECTRIC FA>

<https://www.mitsubishielectric.com/fa/support/index.html>

■ Update history

April 18, 2023

Added modules that have been fixed to "Countermeasures".

R00/01/02CPU, R04/08/16/32/120(EN)CPU

February 28, 2023

Removed annotation of FX5S CPU module from "Affected products" and "Countermeasures".

January 26, 2023

Added modules(FX5UJ, FX5UJ-A, FX5S CPU module) to "Affected products".

Added modules(FX5UJ, FX5UJ-A, FX5S CPU module) that have been fixed to "Countermeasures".

Modified "authorization" to "authentication" in title, "Overview" and "Description".