



TECHNICAL BULLETIN

FA-A-0499-A

[1 / 2]

Production Discontinuation of 10/100/1000M Industrial Switching HUB

■Date of Issue

August 2026

■Relevant Models

NZ2EHG-T8N

Thank you for your continued support of Mitsubishi Electric programmable controllers, MELSEC series.
This technical bulletin informs you that production of the following industrial switching HUB will be discontinued. We appreciate your kind understanding.

1 MODEL TO BE DISCONTINUED

Product	Model
10/100/1000M industrial switching HUB	NZ2EHG-T8N

2 SCHEDULE

Transition to make-to-order: December 26, 2026

Order acceptance: Until February 28, 2027

Production discontinuation: March 31, 2027

3 REASONS FOR DISCONTINUATION

Some parts of this product are becoming difficult to obtain, making it difficult to maintain the production system.

4 REPAIR SUPPORT

Paid repair support period: Until March 31, 2033 (for six years after the discontinuation of production)

If the parts necessary for the repair are not available, we cannot accept the repair order.

5 ALTERNATIVE MODELS

There are no alternative models in our product lineup. Please select a product that is compatible with the CC-Link IE Field Network, as listed on the CC-Link Partner Association website (www.cc-link.org).

Please note that these listed models are considered to be applicable products^{*1} only.

^{*1} A product that satisfies the interface specifications of the modules manufactured by Mitsubishi Electric Corporation. Note that we do not verify these products. Before using the product, examine the applicability and confirm that it will not cause system operation problems. In addition, follow the specifications of the applicable product when using the product.

MITSUBISHI ELECTRIC CORPORATION

HEAD OFFICE: TOKYO BLDG., 2-7-3, MARUNOUCHI, CHIYODA-KU, TOKYO 100-8310, JAPAN
NAGOYA WORKS: 1-14, YADA-MINAMI 5-CHOME, HIGASHI-KU, NAGOYA 461-8670, JAPAN

FA-A-0499-A

REVISIONS

Version	Date of Issue	Revision
A	August 2026	First edition

TRADEMARKS

The company names, system names, and product names mentioned in this technical bulletin are either registered trademarks or trademarks of their respective companies.

In some cases, trademark symbols such as '™' or '®' are not specified in this technical bulletin.