

Notice Regarding Discontinued Production of
Contactors with Built-in Surge Absorber in S-N38(CX)SA/N48(CX)SA Series

1. Discontinued Type

S-N38SA, S-N38CXSA
 S-N48SA, S-N48CXSA

2. Reason for the Discontinuation

Due to discontinued production of surge absorbers

3. Discontinued date

- A. Suspension of orders : The end of March , 2023
- B. Discontinued production : The end of April, 2023

4. Recommended alternative model

Discontinued product			Recommended alternative model				
Type	Rated voltage (50/60Hz)	Varistor Voltage [V]	Type	Rated voltage (50/60Hz)	Type	Designation	Varistor Voltage [V]
S-N38(CX)SA S-N48(CX)SA	AC24V	120	S-N38(CX) S-N48(CX)	AC24V	UT-SA21	AC48V	120
	AC48V	120		AC48V		120	
	AC100V	470		AC100V		AC200V	470
	AC120V	470		AC120V		AC200V	470
	AC127V	470		AC127V		AC200V	470
	AC200V	470		AC200V		AC200V	470
	AC220V	470		AC220V		AC200V	470
	AC230V	470		AC230V		AC200V	470

Notice:UT-SA21 is an optional unit and needed to purchase separately from contactor.

Issue date :October 2022	MITSUBISHI ELECTRIC CORPORATION NAGOYA WORKS, KANI FACTORY 3-5 HIMEGAOKA KANI CITY GIFU PREF. 509-0249 JAPAN TEL. +81-574-61-1952, FAX. +81-574-63-1208
Title Notice Regarding Discontinued Production of Contactors with Built-in Surge Absorber in S-N38SA/N48SA Series	