

[Issue No.] GOT-A-0231-B

[Title] Precautions for the GOT Mobile Function (for Overseas)

[Date of Issue] November 2024 (Ver. B: May 2025)

[Relevant Models] GOT2000 Series (GT27 Models, GT25 Models), GT SoftGOT2000
Version1

Thank you for your continued support of Mitsubishi Electric Graphic Operation Terminal (GOT).
The GOT Mobile function may be influenced by its use environment because of the nature of the specifications.
The influencing factors include the OS, browser type and version, other running applications, and hardware specifications of the information device.
This bulletin provides information on possible symptoms and corrective actions when the GOT Mobile function is used.

Contents

1.	Possible symptoms and corrective actions	1
1.1	Monitoring impossible	1
1.2	Slow response to a user operation	2
1.3	Unintended disconnection	2
1.4	Browser error	2
1.5	No error message appearing upon disconnection	2
1.6	Long and continuous use of the GOT Mobile function	2
1.7	URL entry	2
1.8	Unintended enlargement of the mobile screen	3
1.9	Malfunctioning momentary switch	3
1.9.1	Using the latest version of the software	3
1.9.2	Changing the browser setting	3
1.10	Malfunctioning hyperlink when using the multi-touch function	3
2.	List of validated information devices	3
	REVISIONS	4

1. Possible symptoms and corrective actions

The following lists possible symptoms and corrective actions when the GOT Mobile function is used.
Before using the GOT Mobile function, verify that the function operates properly on your information device.

1.1 Monitoring impossible

If a black screen appears and you cannot start monitoring, check the following items.

(1) Port No.

After you log in from the authentication screen, a black screen may appear and you cannot start monitoring.

If antivirus software is installed on your information device, setting the port No. to 80 or 8080 may cause the access to the server (GOT or GT SoftGOT2000) to fail.

Set the port No. other than 80 and 8080, and then connect the server (GOT or GT SoftGOT2000) again.
For information on how to change the port No., refer to the following.

→ GT Designer3 (GOT2000) Help

(2) Browser operation

If you refresh a browser, the browser may stay at a black screen and no mobile screen appears in some rare cases.

Also, if you switch between browser tabs or perform other operations, an unintended browser refresh may occur, causing the symptom described above.

In such a case, close all browser tabs, restart the browser, and connect the server (GOT or GT SoftGOT2000) again.

1.2 Slow response to a user operation

When you operate a mobile screen or an object on the mobile screen, the response speed and the display refresh rate vary depending on the performance of your information device.

To improve the response speed or the display refresh rate, reduce the number of objects or graph points displayed on mobile screens.

1.3 Unintended disconnection

A browser may be unintentionally disconnected from the server (GOT or GT SoftGOT2000) if you switch between browser tabs or operate other applications.

In such a case, connect the server (GOT or GT SoftGOT2000) again.

If this symptom occurs frequently, close unnecessary browser tabs or exit applications other than the browser.

Doing so may help reduce the occurrence of this symptom.

1.4 Browser error

If the server (GOT or GT SoftGOT2000) has project data containing a lot of mobile screen data, a browser may abend and the access to mobile screens may be unavailable depending on the specifications of the information device.

In such a case, reduce the project data size by deleting unnecessary mobile screens or objects.

1.5 No error message appearing upon disconnection

If you turn off the server (GOT or GT SoftGOT2000) while a browser is accessing the server, the browser may not display a communication error message immediately.

Do not turn off the server (GOT or GT SoftGOT2000) while a browser is accessing the server.

1.6 Long and continuous use of the GOT Mobile function

When you continuously use the GOT Mobile function for a long time, an unintended disconnection may occur.

This symptom possibly occurs if you use a hardware-accelerated browser to access the server (GOT or GT SoftGOT2000) for a long time.

In such a case, disable the hardware acceleration feature in the browser.

If the operation is unstable even without using hardware acceleration, add "reloadtime" to URL parameters and periodically reload the browser.

For information on how to add URL parameters, refer to the following manual.

→ GT Designer3 (GOT2000) Screen Design Manual (SH-081220ENG)

1.7 URL entry

A browser cannot access the server (GOT or GT SoftGOT2000) if you enter only the GOT IP address in the address bar of the browser.

Correctly enter the URL of the server (GOT) in the address bar as shown below.

- When connecting a client to the standard HTTP port No. 80

h t t p : // 1 9 2 . 1 6 8 . 3 . 1 8 / i n d e x . h t m l
Required GOT IP address Optional

- When connecting a client to a user-specified HTTP port (Example: port No. 8080)

h t t p : // 1 9 2 . 1 6 8 . 3 . 1 8 : 8 0 8 0 / i n d e x . h t m l
Required GOT IP address User-specified port No. Optional

1.8 Unintended enlargement of the mobile screen

Depending on your information device, a mobile screen may be enlarged unintentionally at the first display. In such a case, adjust the mobile screen display to fit it to the width of the browser window by using the [Fit Width] button on the operation menu bar. Alternatively, preset the mobile screen size appropriately considering the case that the mobile screen display is enlarged.

1.9 Malfunctioning momentary switch

In either of the following cases, the momentary switch may not operate on the device using Google Chrome as a browser.

- The GOT Mobile function (system application (extended function)) version earlier than 01.50.000 is used.*1

- The GOT Mobile function is used in GT SoftGOT2000 Version1 with a version earlier than 1.300N.

*1 The GOT Mobile function (system application (extended function)) version 01.50.000 or later is stored in GT Designer3 Version1 (GOT2000) with a version 1.300N or later.

In such a case, take either of the following actions.

1.9.1 Using the latest version of the software

Install the latest version of GT Designer3 Version1 (GOT2000) or GT SoftGOT2000 Version1.

For the latest version of the software, consult your local sales office.

1.9.2 Changing the browser setting

Check that [Automatic] is set as the setting value of [Touch Events API] of Google Chrome.

The following describes how to check and change the setting value of [Touch Events API].

(1) For Google Chrome version 78 or earlier

- 1) Enter "Chrome://flags" in the address bar of Google Chrome.
- 2) Enter "Touch Events API" in the search field [Search flags] at upper part of the screen.
- 3) Check that the setting value of [Touch Events API] is set to [Automatic].
When [Disabled] is set, change it to [Automatic].

(2) For Google Chrome version 79 or later

The setting value of [Touch Events API] cannot be checked.

Perform the following operations and start Google Chrome. [Automatic] is set as the setting value of [Touch Events API].

- 1) Create a shortcut to Google Chrome.
- 2) Select [Properties] from the context menu of the shortcut to open the window.
- 3) Append "--touch-events" to the existing string in [Target].
- 4) Click the [OK] button to close the window.

1.10 Malfunctioning hyperlink when using the multi-touch function

When an object with a hyperlink is pressed as the second point of the multi-touch function on iOS, the hyperlink may not operate correctly.

Disabling the popup block setting may improve the situation.

For information on how to disable the setting, refer to the relevant support websites.

■ Safari: Apple Inc. support site

■ Firefox: Firefox help page

2. List of validated information devices

For the devices on which proper operation has been validated by Mitsubishi Electric Corporation, refer to the following.

- List of Devices Validated to Operate with the GOT Mobile of GOT2000 Series (for Overseas) (GOT-A-0196)

REVISIONS

Version	Print Date	Revision
A	November 2024	- First edition
B	May 2025	- Added descriptions to "1.6 Long and continuous use of the GOT Mobile function". - Added "1.10 Malfunctioning hyperlink when using the multi-touch function".

Windows is a registered trademark or trademark of Microsoft Corporation in the United States and other countries.
Android and Google Chrome are trademarks or registered trademarks of Google Inc.
Apple is a trademark of Apple Inc, registered in the United States and other countries.
iPad is a trademark of Apple Inc.
IOS is a trademark or registered trademark of Cisco in the U.S. and other countries and is used under license.
Safari is a trademark of Apple Inc. registered in the United States and other countries.
Other product and company names are either trademarks or registered trademarks of their respective owners.