TECHNICAL NEWS

[Issue No.] LVS-YE-0005-A

[Page] 1/1

ITitle] About the influence of cancellation of PA/PET resins of Toyobo Co., Ltd. to our Circuit **Breakers**

[Date of Issue] September 2025

[Relevant Models] Low Voltage Molded Case Circuit Breakers / Earth Leakage Circuit Breakers

Regarding the resin material used in our popular Molded Case Circuit breakers and Earth Leakage Circuit Breakers, we have announced a review of the UL94 flame retardant grade following the material manufacturer's revocation of UL certification (Issue number LVS-YE-0005, issued in March 2021). We would like to inform you that our future response to the material manufacturer's re-certification as follows.

1. Affected models / parts / Time of change

Due to the material manufacturer's re-certification of applicable UL certification, the UL94 flame retardancy

grade of applicable models and parts will be changed from "V-2" to "V-0".

Series	Model names			Parts (Materials))	Time of Change
WS-V	Molded Case Circuit Breakers F Style		NF32-SVF NF63-CVF, NF63-SVF	- Handles	From production
	Earth Leakage Circuit Breakers F Style		NV32-SVF NV63-CVF, NV63-SVF		
	Earth Leakage Circuit Breakers F Style CE·CCC models		NV32-SVF NV63-CVF, NV63-SVF		
	Motor Protection Breakers	МВ	NF63-SVF	(PA resin)	İn August 2026.
	Earth Leakage Circuit Breakers for motor protection		NV63-SVF		
	UL 489 Listed Circuit Breakers F Style		NF50-SVFU		
	UL 489 Listed Circuit Breakers with earth leakage protection F Style		NV50-SVFU		
	Molded Case Circuit Breakers		NF63-SV, NF63-HV 4P 10∼50A	- Base	From production
	Earth Leakage Circuit Breakers		NV32-SV 5A,6A NV63-CV, NV63-SV 5A		
	Earth Leakage Circuit Breakers for	MB	NV63-CV, NV63-SV 4 \sim 8A	(PET resin)	In April 2026.
	motor protection	PR	NV63-CV, NV63-SV 2~ 8A		
	DSN Switches		DSN63-SV 4P 50A		

^{*}Please note that specific purpose circuit breakers (Mag-Only, DC special voltage Circuit Breakers) are also

^{*}The change in flame retardant grade will not affect installation or performance.

^{*} Please bear in mind that the exact start of production may change due to inventory situation.