

TECHNICAL NEWS

[Issue No.] LVS-YE-0011

[Page] 1/1

[Title] Regarding Medium-Chain Chlorinated Paraffin (MCCP)

[Date of Issue]

[Relevant Models] Circuit protector

We would like to inform you as follows regarding our response to the presence of Medium-Chain Chlorinated Paraffin (MCCP) in optional parts for circuit protectors you are currently using.

1. Relevant models

The insulating caps supplied with the BT-CPA back facing wiring terminals (for 20A or less and 30A) for circuit protectors (CP30-BA, CP30-HU) are subject to this notice.



Insulating caps

2. Response to the presence of Medium-Chain Chlorinated Paraffin (MCCP)

We are planning to change the materials for the applicable products listed in the table below.

Model	Before the revision	After the revision
Insulating caps supplied with the back facing wiring terminals (BT-CPA) for CP30-BA and CP30-HU	Contains	Not contained

There are no differences in appearance or product performance due to the material change.

Other than the BT-CPA, no other circuit breakers, circuit protectors, or their accessories contain MCCP.

3. Future Actions

We plan to switch to non-MCCP-containing products starting from the June 2026 production. However, depending on our inventory levels and market stock, MCCP-containing products manufactured prior to the changeover may continue to be shipped even after the changeover timing.

MITSUBISHI ELECTRIC CORPORATION

HEAD OFFICE : TOKYO BUILDING, 2-7-3 MARUNOUCHI, CHIYODA-KU, TOKYO 100-8310, JAPAN
FUKUYAMA WORKS : 1-8, MIDORIMACHI FUKUYAMA-CITY HIROSHIMA-PREF. 720-8647, JAPAN