

## Production Discontinuation of MELIPC MI5122-VW, MI2012-W, MI2012-W-CL, and Related Products

### ■Date of Issue

May 2025

### ■Relevant Models

MI5122-VW, MI2012-W, MI2012-W-CL, MI5A1P, MI5FAN, CW Workbench 4

Thank you for your continued support of Mitsubishi Electric industrial PC, MELIPC series.

We announce that MELIPC MI5122-VW, MI2012-W, MI2012-W-CL, and related products will be discontinued, as explained below.

## 1 MODEL TO BE DISCONTINUED

Product	Model
MELIPC	MI5122-VW, MI2012-W, MI2012-W-CL
Power supply module	MI5A1P
Fan module	MI5FAN
CW Workbench 4	SW1DND-CWW4-E, SW1DND-CWW4-EZ, SW1DND-CWW4-EVZ

## 2 SCHEDULE

- Transition to made-to-order: April 25, 2025
- Order acceptance: Through March 31, 2026
- Production discontinuation: April 30, 2026

## 3 REASONS FOR DISCONTINUING PRODUCTION

The installed operating system is no longer supported, and we will not be able to maintain our production system.

## 4 REPAIR ACCEPTANCE

### MI5122-VW, MI5A1P, MI5FAN

- Repair support period: Until April 30, 2033 (for seven years after the discontinuation of production)

### MI2012-W, MI2012-W-CL

- Repair support period: Until April 30, 2031 (for five years after the discontinuation of production)


This is because MI2012-W and MI2012-W-CL are developed and manufactured by Mitsubishi Electric Corporation in collaboration with Advantech Co., Ltd.

## 5 MODEL RECOMMENDED FOR REPLACEMENT

Model to be discontinued	Model recommended for replacement
MI5122-VW	MI2532-W
MI2012-W, MI2012-W-CL	MI2332-W

AC adapters and power cables for AC adapters are not included with models recommended for replacement.

For the specifications of the models recommended for replacement, refer to the following:

 MI2532-W/MI2332-W User's Manual

### REVISIONS

Version	Date of issue	Revision
A	May 2025	First edition

### TRADEMARKS

The company names, system names and product names mentioned in this bulletin are either registered trademarks or trademarks of their respective companies.

In some cases, trademark symbols such as '™' or '®' are not specified in this bulletin.