

TECHNICAL BULLETIN

[Issue No.] FA-A-0010

[Page] 1/1

[Title] Production discontinuation of the printer
and relational devices

[Date of Issue] Jan., '08

[Relevant Models] A7NPR-S1, A7NPR-S1-R, A7PR-R, K6PR-K-S1-R, K7PR-R, K6PR-Y, K7PR-Y,
K7PR-Y-S1

Thank you for your continued support of Mitsubishi programmable controllers, MELSEC-A/K series.

Production of the following printer and relational devices will be discontinued.

1. Models to be discontinued

Product	Model	Description	Remarks
Printer (Main unit)	A7NPR-S1*1	For connecting to A6CGT Printing is possible.	A6CGT has been discontinued. (Note 1)
Printer ribbon	A7NPR-S1-R	A7NPR-S1 printer ribbon	—
	A7PR-R	A7PR ink ribbon	A7PR has been discontinued. (Note 2)
	K6PR-K-S1-R	K6PR-K-S1 printer ribbon	K6PR-K-S1 has been discontinued. (Note 3)
	K7PR-R	K7PR printer ribbon	K7PR has been discontinued. (Note 4)
Printer paper	K6PR-Y	K6PR printer paper	K6PR has been discontinued. (Note 4)
	K7PR-Y	K7PR printer paper	K7PR has been discontinued. (Note 4)
	K7PR-Y-S1	K7PR printer paper	K7PR has been discontinued. (Note 4)

(Note 1) Refer to TECHNICAL BULLETIN T99-0003

(Note 2) The A7PR has been discontinued with the introduction of alternative product, the A7PR-S1 in 1988.

(Note 3) Refer to TECHNICAL BULLETIN T99-0027

(Note 4) Refer to TECHNICAL BULLETIN T99-0001

*1: We recommend considering using GX Developer and a commercially available printer for printing.
GX Developer can read a sequence program when setting the ACPUs series for the programmable controller.
For printing the sequence program, connect GX Developer to the commercially available printer.

<Unsupported CPUs>

A1CPU, A2CPU, A3CPU, A3HCPU, A3MCP, A3VCP, A52GCP, A73CPU, A0J2CPU

2. Schedule

- Order acceptance Through September, 2008
- Production discontinuation Through December, 2008

3. Reasons for discontinuing production

The demand for the dedicated printers has been reduced. Therefore, we will have difficulty to maintain the production system.

4. Repair acceptance

Repair acceptance of printer: Through December, 2015 (For 7 years after production discontinuation)

We may not repair the printers depending on the conditions.

Printer ribbon and printer paper: We do not deal with the repair since the parts are deteriorated and consumed.