

Indication change of ACB


We would like to inform that we will change the indication for ACB.

1. Types

Mechanical interlock (MI) for AE-SW.

2. Content of the change

Change the caution label to bilingual (Japanese and English).



Before the change	After the change
<p>■ <u>English only</u></p> <p>•MI for 2units(MI2)</p> <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p style="text-align: center;">CAUTION</p> <p>This breaker is mechanically interlocked. DO NOT CLOSE TWO BREAKERS AT SAME TIME.</p> <p style="text-align: right; font-size: small;">LN417N344H01</p> </div> <p>•MI for 3units(MI3)</p> <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p style="text-align: center;">CAUTION</p> <p>This breaker is mechanically interlocked for among 3 ACBs. Do not close three breakers at same time.</p> <p style="text-align: right; font-size: small;">LN417N344H03</p> </div>	<p>■ <u>Bilingual (Japanese and English)</u></p> <p>•MI for 2units(MI2)</p> <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p style="text-align: center;">注意 CAUTION</p> <p>この遮断器はメカニカルインターロック付です。 他方の遮断器と同時投入しないでください。 This breaker is mechanically interlocked. Don't close two breakers at the same time.</p> <p style="text-align: right; font-size: small;">LN417N344H02</p> </div> <p>•MI for 3units(MI3)</p> <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p style="text-align: center;">注意 CAUTION</p> <p>この遮断器は3台用メカニカルインターロック付です。 3台の遮断器を同時投入しないでください。 This breaker is mechanically interlocked for among 3 ACBs. Don't close three breakers at the same time.</p> <p style="text-align: right; font-size: small;">LN417N344H04</p> </div>

3. Reason for change

In order to improve productivity.

4. Time of change

Production starting from April 2024.

(Please be noted that the time of change may be advanced or delayed.)